RULES TO LIVE BY

Slopes are a major factor related to loss-of-control and tip-over accidents, which can result in severe injury or death.

Follow the instructions in your machine's Operator's Manual when driving on slopes.

- **Avoid starting, stopping or turning on a slope**. If you lose traction, proceed slowly, straight down the slope.
- **Avoid holes, ditches, and obstructions** which causes the machine to tip, especially on slopes. Avoid sharp uphill turns.
- Do not travel up or across a slope steeper than 15°, Make sure that the tracks are extended to their widest position, providing the broadest stance for the machine.
- Keep attachments as low as possible when traveling on slopes or rough terrain.
- Keep the heavy end of the machine towards the uphill direction when traveling up or down a slope.

  NOTICE: *When the machine has no attachment or load, the heavy end is the operator's platform end of the machine.*





© 2020 Boleo Corporation